



Bicycle Oiler Jockey Wheel Compatibility

Shimano MTB

Model	Jockey Wheel	Plate
XTR (M960, M970, M971)	JW No. 4	M5 Plate
XT (M760, M761)	JW No. 4	M5 Plate
Saint (M800, M801, M805, M806)	JW No. 4	M5 Plate
Hone (M600, M601)	JW No. 4	M5 Plate
LX (M580, M581)	JW No. 4	M5 Plate
Deore (M510, M511, M530)	JW No. 4	M5 Plate
Alivio (MC20)	JW No. 4	M5 Plate
Alivio 06 (M410)	JW No. 4 *	M5 Plate
Acera (M340)	15 Tooth Jockey Wheel, not included in standard kit **	
Altus (CT95)	15 Tooth Jockey Wheel, not included in standard kit **	
Tourney (TX30, TX50, TX70)	15 Tooth Jockey Wheel, not included in standard kit **	
Tourney (FT30)	JW No. 4	M5 Plate

* Original JW is 13 Tooth but JW No. 4 can be used.

** For these models, contact Scotttoiler for a replacement 15 Tooth Jockey Wheel.

Shimano Road

Model	Jockey Wheel	Plate
Dura Ace 10sp (R7800)	JW No. 4	M5 Plate
Dura Ace 9sp (R7700)	JW No. 4	M5 Plate
Ultegra (6600)	JW No. 4	M5 Plate
105 10sp (5600)	JW No.4	M5 Plate
105 9sp (5501)	JW No. 4	M5 Plate
Tiagra (4400, 4500)	JW No. 4	M5 Plate
Sora (3300)	JW No. 4	M5 Plate
RD-2200	JW No. 4 *	M5 Plate
A050	JW No. 4 *	M5 Plate

* Original JW is 13 Tooth but JW No. 4 can be used.

Campagnolo Road

Use JW No. 1 and an M5 Plate – suits all 9sp & 10sp Campag

SRAM

Model	Jockey Wheel	Plate
X0 (2003 – 2005 & 2006 - 2007)	JW No. 4 with Bush No.1	M6 Plate
X9 (2005-2007)	JW No. 4 with Bush No.1	M6 Plate
X9 (2004)	Not Compatible	
X7 (2005 - 2007)	JW No. 4 with Bush No.1	M5 Plate
X7 (2004)	Not Compatible	
SX5 (2006 - 2007)	JW No. 4 with Bush No.1	M5 Plate
SX4 (2006 - 2007)	JW No. 4 with Bush No.4	M5 Plate
9.0 SL (2001 - 2002)	Not Compatible	
7.0 & 9.0 (2001 - 2003)	Not Compatible	
5.0 (2001 - 2005)	Not Compatible	
4.0 (2003 – 2005)	Not Compatible	
3.0 (2003 - 2006)	Not Compatible	
Dual Drive 27 (2004-)	JW No. 4 with Bush No.1	M5 Plate
Dual Drive 24	Not Compatible	
Dual Drive 21	Not Compatible	

SRAM Rival and Force Road mech compatibility TBC

Current Product innovation is pursuing the possibility of a non Jockey Wheel based system for Mountain Bikes & incompatible rear mechanisms, contact us for further information.

If you have any further comments or queries please do not hesitate to call technical on 0141 955 1100 or email cycling@scottoiler.com for assistance. Thank you.
Scotttoiler Ltd. 2 Riverside, Milngavie, Glasgow, G62 6PL Tel. 0141 955 1100 Fax. 0141 956 5896 www.scottoiler.com